

Patching Kit 200 ml Operation Manual

Before lacquering you should:

- Prepare painted surface, degrease the place for painting with means of degreasing agent located in the kit and degreasing cloth.
- When damage is too deep, you should use primer to protect it against corrosion.
- Mix the paint in the package by shaking it for about one and a half minute.
- Application brush is located in the closing of paint package.
 - Make the painting with small amount of paint at test card attached to the kit, to compare the paint tone with colour of painted surface.
 - Place two to three thin layers of paint and maintain interval of about 2 minutes between placing subsequent layers, according to environmental conditions.
- Temperature for placing the paint should be 5C - 25C with regard to air humidity.